


TECHNICAL SERVICE BULLETIN

NO. 73-A-4



March, 1973

SUBJECT:

CONNECTING RODS

MODELS:

1275 cc A SERIES ENGINE
1800 cc B SERIES ENGINE

Connecting rods for the above engines supplied as service replacements are equipped with hexagonal nuts for transit purposes only.

When fitting replacement rods, the hexagonal nuts **MUST BE DISCARDED** and replaced by the correct multi-sided nuts, part no. 13H 5872.

SB-A 2/21/73